

SECRET

OXC 5768

1 October 1963

MEMORANDUM FOR: Chief, Security Staff
SUBJECT : Security Fencing at Eielson AFB

25X1A

1. During the recent visit to Eielson AFB by several members of the Headquarters Staff, and [] from [], it was noted that the security fencing surrounding the OXCART hangar does not include a gate across the taxiway leading into the hangar. It was the unanimous opinion of all present that in the absence of any manned guard post at this point, total enclosure is demanded.

25X1A

2. On 30 September I received a call from [] on this subject. He had discussed the matter of a gate with the foreman in charge of construction of the new OXCART building immediately adjacent to our hangar. [] was advised that there were no provisions in the original construction specifications for such a gate and that furthermore no steps are being taken to erect such a gate, to the best of the foreman's knowledge.

25X1A

3. I suggest you might wish to discuss this matter further with [] and if you then agree that a gate is needed, take steps to assure that the construction contract is amended to provide for it.

25X1A

[]

25X1A

[] Acting Chief
Support Division, OSA

25X1A

SD;OSA:[] bwl

Distribution:

Orig - C/SS/OSA
2 - SD/OSA
3 - DAD/OSA
4 - C/Mat/OSA
5 - RI/OSA

DOCUMENT NO. []
NO CHANGE IN CLASS. []
[] DECLASSIFIED
CLASS. CHANGED TO: TS S C []
NEXT REVIEW DATE: []
AUTH: HR 70-2 []
16274 REVIEWER: 010956

SECRET